

## Kwik-File, LLC Tambour Door Replacement

1. Remove bottom pan by lifting up on



2. Remove one insert panels by removing the (4) screws Note: When replacing insert panels, two rectangles on insert should be placed to back side of console.

(Fig 1.2)




Kwik-File, LLC
490 Northco Drive


Minneapolis, MN 55432
Phone: 1-800-822-8037
Fax: 920-457-7388
Online: www.mayline.com

3. Remove center door stops.

## (Fig 1.3)



4. Slide both doors to one side of cabinet. Remove top & bottom track from the side that you removed the end panel from (**Fig 1.4**)



- 5. Slide both doors out of cabinet.
- 6. Unpack doors for cabinet and assemble slam rails to door slats.

Note: For 36" Consoles, remove 18 slats from both right and left hand doors.

7. Slide new doors back into the track that was left in place.

Note: Right hand door has the lock installed into the slam rail.

Reverse the previous steps starting at step 4 to step 1.